Executive Sales Manager Jean Jacques Soete
yacht@abyacht.com
Whatsapp : +33 611 354 611 / + 44 1414 160 507

Brokerage / Charter / New construction
Commercial vessel / Xbow
Conversion / Refitting / Management Flag / Surveyor

Motoryacht Baglietto 43 M 2009 refitted 2020 and 2023
Asking price 11.800.000 € vat paid



Builder : *Baglietto Shipyard*
LO A : *42.75 M*

TIAMAT is a highly sought-after charter yacht with bookings already secured for 2025.

The vessel is expertly managed by a German Captain and a dedicated crew of six, all eager to remain onboard if the yacht is sold
— ensuring seamless continuity for her next owner.

Currently located in France, TIAMAT is available for viewings at your convenience.

KEY – FEATURES:

- *11.800.000,00 €*
- *VAT paid*
- *15-year ABS Survey done in 2024*
- *Entirely painted 2020 / New Teak decks in 2022*
- *Commercial compliant*
- *Transatlantic range*
- *New Jacuzzi installed in 2024*

Transatlantic Range
15-year ABS-Survey completed in 2024
Extensive Refit in 2020 & 2023
Beach club with sauna
Jacuzzi on Sun-Deck

Main Characteristics

BUILDER	***Baglietto Shipyard Italy***
Model	***Baglietto T-LINE 43 M***
TYPE	***3 decks***
HULL TYPE	***Displacement***
NAVAL ARCHITECT	***Baglietto SPA***
EXTERIOR DESIGNER	***Francesco Paszkowski***
INTERIOR DESIGNER	***Art Line Design***
YEAR	**2009**
REFIT	***2020 & 2023***
CLASSIFICATION	***Abs commercial / MCA Compliant***
MATERIAL HULL	***Steel***
MATERIAL SUPERSTRUCTURE	***Aluminium***
CREW	***Up to 11 in five cabins***
FLAG	***Marshall Islands***
GT	***419***
LOCATION	***France***

Dimensions

LOA	*42.75 M*
LWL	*38.40 M*

Beam : *8.90 M*
Draft : *3.00 M*

Speed and range:

Maximum speed *17.00 knots*
Cruising speed: *12.00 knots*
Economical cruising speed: *10 Knots*
Range : *4500 NM at 12 knots*

Accommodation

Guests : 5 cabins up to 12 berths
: 3x Double beds
: 4x Single beds

Crew : 6 cabins up to 11 berths

Mechanical Equipment:

TRIM TABS
BOW THRUSTER
STABILIZERS
ENGINE COMPARTMENT Fan
FUEL PURIFIER

ENGINE X 2 ***Caterpillar /CAT 3512***
Builder ***Caterpillar /CAT 3512***
TYPE ***Diesel Turbo 12 cylinder***
POWER ***1800 KW 2447 PS***
ENGINE HOURS ***5800 (20/11/2024***
DRIVE ***Shaft X 2***
PROPELLER ***5 blade X 2***

GENERATOR X 2 `

Builder ***Cat /Caterpillar X 3***
Type ***diesel/ sound cover***
Power ***86 KW X 3*** ***Engine hours : 5233 (14/11/024)***
: 7219 hours
: 12254 hours

TEAKDECK	***Foredeck, Gangboard, Stairs to the bathing , Platform, Bathing platform, Cockpit, Aft deck, Fly Bridge, Skydeck***
REELING	***Sea Railing, wooden handrail***
ANCHOR WINCHES	***Bow (2X el control***
ANCHOR 1	***Yes***
ANCHOR 2	***Yes***
WINCHES	***2***
WINDOW	***Windshield wiper (3x), Windshield washer system, Front window blower***
RADAR ARCH	***Yes***
CRANE	***Davit in bow area, 600 kg Lifting power***
GARAGE	***Converted to Sauna***
HYDR. PLATFORM	***With lifting capacity of 1200 KG***
GANGWAY S	***Custom***
SIDE-GANGWAY	***Opacmare***
BATHING LADDER	***Integraded***
DECK WASHING SYSTEM	***Yes***

Interior

BATHROOMS	***X 6***
DAYHEAD	***X2***
SAUNA/STEAM	***Yes***
BATH BATHTUB	***Yes***
DINING AREA	***Yes***
PILOTHOUSE	***Yes***

Exterior

Sundeck	*Seating group,* *Table,* *Jacuzzi,* *Sun pads,* *Sun awning,* *Icemaker,* *Sink,* *Refrigerator,* *BBQ,* *Hardtop roof,* *Bimini Top*
Sundeck	*Seating group,* *Lounge,*

	Table, *Sun pads,* *Sun awning*
Foredeck	*Yes*
Afterdeck	*Sitting group, table* *Deck saloon* *Pilothouse* *Side doors*

Galley

HOB	*Induktion*
MICROWAVE	***Yes***
OVEN	***Yes***
COFFEE MAKER	***Yes***
EXTRACTOR HOOD	***YES***
SINK	***yes***
DISHWASHER	***Yes***
FOOD ELEVATOR	***YES***
REFRIGERATOR	***YES***
WINE Cooler	***YES***
FREEZER	*YES*
ICE MAKER	***YES***

Laundry

WASHING MACHINE
DRYER

Crew

CREW AREA	***FORESHIP***
PANTRY	***Stove, sink, fridge***
CABINS	***6***
BERTHS	***11***
BATHROOMS	***6***

Tender & Jetski

Tender	***Enma 730 RIB***
Jetski	***Yamaha***

Nautical

ECHO SOUNDER	***SPERRY marine***
FISHFINDER	***RYMARINE***
SUMLOG	***YES***
COMPASS	***YES***
AUTOPILOT	***YES***
CHARTPLOTTER	***SAAB***
GPS	*SAAB*
AIS	***YES***
RADAR	***SAAB***
IMERSAT	***C SAILOR TT 3603606E***

WIND MEASURING SYSTEM	***yes***
RUDDER ANGLE INDICATOR	***yes***
SPOTLIGHTS	***yes***

Communication

SAT-KOM
VHF RADIO
STARLINK INTERNET
Search spotlight (electric, 1x)

Electrical equipment

POWER SUPPLY : Shore connection, Cable master, Electrical system 230 V, Chargers, Battery main switch

LIGHTING

Deck lighting, Underwater spotlights (6x), Navigation lights

TV / AUDIO

SAT antenna (Cobham VSAT 600), TV (9x)

Water / Climate / Heating

WATER SYSTEM

Pressurized water system, Seawater treatment (290 Liters/h), Wastewater treatment, Warm water system

AIR CONDITIONING SYSTEM

Type: Heating / cooling

Safety

DISTRESS SIGNAL DEVICES
ONBOARD PHARMACY
ANCHOR BALL
EPIRB TRANSMITTER
DRAG LINE
FIRE EXTINGUISHER
LIFEBELT
RESCUE FLOAT
LIFE JACKETS
LIFE RAFTS
BOAT HOOKS
FENDER
ROPES
EXTINGUISHING SYSTEM
ENGINE ROOM
FIRE ALARM SYSTEM
VESSEL MONITORING
CAMERA SYSTEM
NIGHTVISION CAMERA SYSTEM
BILGE PUMP

OTHER

MCA Compliant

Refit

REFIT 2018 - 2020

Owners cabin

1. Replacement of flooring with a painted floor covering
(Stripping to shiny metal)
2. Carpet Replacement
3. Reconstruction of the sofa, with the addition of furniture elements
4. Replacement of the bed foundation, and the whole bed (new made)
5. Complete replacement of the ceiling covering with a new one (Alcantara) with the modernization and manufacturing of individual elements of the ceiling.

6. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system. (new)
7. Complete modernization and reconstruction of the bathroom, (replacement of marble, flooring with a painted floor covering (Stripping to shiny metal), dismantling and removal of the bath, installation of a new shower cabin with a steam generator inside (hammam)

8. Modernization of blind portholes in the bathroom and wardrobe (modernized and installed opening portholes, with automatic mechanisms for opening and closing the porthole)
9. Replacement of air conditioner control panels with new ones (touchscreen).

10. Replacement of the stereo and TV systems with new ones.
11. Partial replacement of the electrical wiring with a new one (35% replaced)
12.Replacement of all luminaires.
13.Replacement of all furniture fittings.

Salon Main Deck

1. Carpet Replacement
2. Replacement of old sofas with new ones

3. Complete replacement of the ceiling covering with a new one (Alcantara) with the modernization and manufacturing of individual elements of the ceiling.
4. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system. (new)

5. Replacement of air conditioner control panels with new ones (touchscreen). 6. Replacement of the stereo and TV systems with new ones.
7. Movie theater screen installation (JVC – Reference Series)
8. Partial replacement of the electrical wiring with a new one (25% replaced) 9. Replacement of all luminaires.

10. Replacement of all furniture fittings.
11. Restoration of furniture paintwork, with partial replacement and preparation of new furniture elements.

Lower Deck
Lobby
1. Modernization and replacement of decorative elements, wall coverings. 2. Complete replacement of the ceiling covering with a new one (Alcantara). 3. Replacement of the old carpet flooring with a new one (oak flooring).
4. Replacement of the old staircase carpet with a new one (oak flooring).
5. Replacement of lightening elements (lamps and luminaires).

VIP Port Cabine

1. Modernization and replacement of decorative elements, wall coverings.
2. Complete replacement of the ceiling covering with a new one (Alcantara).
3. Replacement of the old carpet flooring with a new one.
4. Replacement of lightening elements (lamps and luminaires).
5. Replacement of the old headboard covering on the bed with a new one.
6. Replacement of the old sofa covering with a new one.
7. Replacement of the stereo and TV systems with new ones.
8. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system (new).

VIP STB Cabine

1. Modernization and replacement of decorative elements, wall coverings.

2. Complete replacement of the ceiling covering with a new one (Alcantara). 3. Replacement of the old carpet flooring with a new one.
4. Replacement of lightening elements (lamps and luminaires).
5. Replacement of the old headboard covering on the bed with a new one. 6. Replacement of the old sofa covering with a new one.

7. Replacement of the stereo and TV systems with new ones.
8. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system (new).

Twin Port Cabin

1. Modernization and replacement of decorative elements, wall coverings.
2. Complete replacement of the ceiling covering with a new one (Alcantara).
3. Replacement of the old carpet flooring with a new one.
4. Replacement of lightening elements (lamps and luminaires).
5. Replacement of the old headboard covering on the bed with a new one.
6. Replacement of the old sofa covering with a new one.
7. Replacement of the stereo and TV systems with new ones.
8. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system (new).

Twin STB Cabine

1. Modernization and replacement of decorative elements, wall coverings.
2. Complete replacement of the ceiling covering with a new one (Alcantara).

3. Replacement of the old carpet flooring with a new one.
4. Replacement of lightening elements (lamps and luminaires).
5. Replacement of the old headboard covering on the bed with a new one.
6. Replacement of the old sofa covering with a new one.
7. Replacement of the stereo and TV systems with new ones.
8. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system (new).

Bridge Deck Saloon Bridge Deck

1. Replacement of flooring with a new one (oak flooring).
2. Reconstruction of the sofa, with the addition of furniture elements.
3. Complete replacement of the ceiling covering with a new one. (Alcantara) with the modernization and manufacturing of individual elements of the ceiling.
4. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system (new).
5. Replacement of air conditioner control panels with new ones (touchscreen).
6. Replacement of the stereo and TV systems with new ones.
7. Partial replacement of the electrical wiring with a new one (20% replaced)
8. Replacement of lightening elements (lamps and luminaires).
9. Replacement of all furniture fittings.
10. Furniture paintwork restoration, with partial replacement and preparation of new furniture elements.

Corridor and stairs

1. Replacement of flooring with a new one (oak flooring).
2. Complete replacement of the ceiling covering with a new one. (Alcantara) with the modernization and manufacturing of individual elements of the ceiling.
3. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system (new).
4. Replacement of air conditioner control panels with new ones (touchscreen).
5. Partial replacement of the electrical wiring with a new one (5% replaced)
6. Replacement of lightening elements (lamps and luminaires).
7. Replacement of all furniture fittings.
8. Furniture paintwork restoration, with partial replacement and preparation of new furniture elements.

Pilothouse

1. Replacement of flooring with a new one (oak flooring).

2. Complete replacement of the ceiling covering with a new one (faux leather) with modernization and manufacturing of individual elements of the ceiling.
3. Replacement of all ventilation ducts, supply, and exhaust ventilation systems, including ducts of the air conditioning system (new).

4. Replacement of air conditioner control panels with new ones (touchscreen).
5. Partial replacement of the electrical wiring with a new one (40% replaced)
6. Replacement of lightening elements (lamps and luminaires).

7. Furniture paintwork restoration, with partial replacement and preparation of new furniture elements.

8. Full replacement of the yacht monitoring system with a new one. 9. Complete replacement of all navigation monitors equipment.
10. Installment of additional echo sounder Raymarine.
11. Installment of fish finder Raymarine.

12. Replacement and installation of a new yacht server.
13. Replacement of navigator's chairs with new ones.
14. Installation of a new video surveillance system, that has 14 new cameras and two underwater cameras, which transmit information to the monitor about the state of the steering group propeller.
15. Installation of a FLIR night vision system.
16. Replacement with a new VHF station.
17. Installation of a new navigation system TRANSAS.
18. Replacement of the motor control controller (telegraph) (front and backward movement), installation of a new one (REXROTH manufacturer)

Crew Mess:

1. Addition of a new cabin. The crew cabins now can fit 10 crew members, not counting the captain's cabin. Captain's cabin is located on the bridge.
Exterior

Yacht hull
1. All problem areas of the exterior have been restored. (rust, cracks, damaged putty areas)

2. The entire hull of the yacht was repainted.

Mast Deck
1. Installment of the satellite internet antenna Cobham VSAT 600 Ku.

Sun Deck

1. Jacuzzi dismantled and removed.
2. Dismantled and removed the bar counter.
3. The dining table was dismantled and replaced with a new, handmade, made of milk natural granite, interspersed with natural gold.
4. Replacement of chairs at the dining table.
5. Sunbeds were installed.
6. Replacement of teak across the whole Sun Deck area.
7. Redesigned sofa Cushions
8. Installment of the sun protective awning.
9. Replacement of lamps.
10. Installation of LED feed.
11. Installation of additional crane.

Pilothouse External

1. The dining table was dismantled and replaced with a new, handmade, made of milk natural granite, interspersed with natural gold.
2. Replacement of chairs at the dining table.
3. Replacement of teak across the whole area.

4. Installment of the TV
5. Redesigned sofa Cushions
6. Installment of the sun protective awning. 7. Modernization of the opening of ceilings. 8. Replacement of lamps.
9. Installation of LED feed.

Bridge Deck Forward

1. Sunbathing pad was dismantled. Instead, four sealed lockers have been designed. Two hermetically sealed for storage of equipment and property of the yacht, the area of 5.5 square meters were installed. And two hermetically sealed lockers for garbage storage, with the volume of 0.75 cubic meters.

2. Modernization of the laundry, replacement of the old equipment. Installation of the new working pieces.

Main Deck External

1. Redesigned sofa Cushions
2. Modernization of the opening of ceilings.
3. Replacement of teak across the whole area. 4. Replacement of lamps.
5. Installation of LED feed.

Stern Swimming Area

1. Modernized and raised up by 30 centimeters.
2. Replacement of teak across the whole area.
3. Installment of descending hydraulic swimming platform, with a lifting capacity of 1200 kg.
4. Installment of 8 Lumishore underwater lights.

Stern Garage

1. Modernized into the beach club.
2. Installment of sauna.
3. Modernization of the gangway, lengthened by 1.20 meters

Engine room

1. Old diesel generators No. 1 and No. 2 Caterpillar (power 86 kW) were dismantled.
2. New No.-1 and No.-2 Caterpillar installed, power 98 kW.

3. Diesel generator Caterpillar No - 3 was modernized. The generator was replaced from 50 kW to 86 kW.
4. Replacement of the old synchronization system of diesel generators and DAIF load distribution with the new DAIF system 2020.

5. The old LUTRON lighting control system was dismantled. Replaced with a new modern smart home system CONTROL - 4.





















